



## Component Maintenance Manual for Coupling Products

<u>CMM No.</u>	<u>NORCO P/N</u>	<u>REVISION</u>	<u>DATE</u>
54-35-53	A1149-1, A1208-1, -3	A	Jun 01/98
54-50-01	A3474-27	A	June 6/14
71-10-10	A2733-1, -2	B	Mar 23/07
71-10-12	A2724-3, -5	F	May 31/04
71-10-13	A2739-5, -8	D	Apr 01/98
71-10-14	A2739-6	N/C	Oct 30/81
71-10-15	HR2797-2	N/C	Feb 01/83
71-10-16	A2785-1	B	Jan 01/97
71-10-17	A2786-1	B	Jan 01/97
71-10-18	A2866-3, -4	E	Apr 15/10
71-10-20	A2841-1	N/C	Apr 01/83
71-10-21	A2776-1A	A	May 15/86
71-10-24	A2785-12, -14, -15, -16	K	Nov 11/11
71-10-27	A2974-1	A	Oct 22/02
71-10-28	A2880-1, A2882-2	A	Jan 19/98
71-10-29	A3056-1	N/C	Mar 15/87
71-10-33	A2711-1 (thru) -11	B	Jun 15/98
71-10-34	A2711-16	A	Jun 15/98
71-10-35	A2711-15, -17	B	Jun 15/98
71-10-36	A2764-1, -3, -16, -17	G	May 31/04
71-10-37	A2955-11, -12	C	Feb 15/02
71-10-38	A2739-1, -2	N/C	Sep 01/89
71-10-39	A2956-4, -5, -5A, -6	F	JAN 19/11
71-10-40	A6201-2, -3, -32	H	Mar 11/15
71-10-41	A6501-2, -3	B	April 24/02
71-10-42	A2957-10	N/C	Jan 01/90
71-10-43	A2898-1, -3	B	Nov 01/00
71-10-44	A2724-1	A	Oct 1/92
71-10-45	A1108-580-325A, -325B A1108-610-340A, -340B	A	Nov 01/99
71-10-46	HR2769-6, -8	C	Apr 01/99
71-10-47	A361-3C, -6	A	JAN 19/10
71-10-48	A3295-1, -2	D	May 23/07
71-10-49	A3312-3	D	Feb 14/02
71-10-50	A3370-30, -301	B	Jul 26/05
71-10-51	A3370-60, -601	C	Dec 29/00
71-10-52	A3396-10, -101	B	Sept 7/17
71-10-53	A3293-4	N/C	May 01/94
71-10-55	A3407-40, -401, -701	E	Aug 01/02
71-10-56	A3427-10, -101	A	Apr 01/96
71-10-57	A3428-10, -101	B	Jul 12/11
71-10-58	A3482-1, -2, -4	H	Feb 4/15
71-10-60	A3348-039, -049, -059	B	Feb 01/01



<u>CMM No.</u>	<u>NORCO P/N</u>	<u>REVISION</u>	<u>DATE</u>
71-10-62	A3410-2	G	May 28/14
71-10-63	A3372-1	B	Feb 20/02
71-10-64	A3497-7, -8	N/C	Jan 01/99
71-10-66	A3550-7, -8	A	Mar 1/02
71-10-67	A3363-4, -5	A	Sept 23/10
71-10-68	A3409-2	D	Dec 11/09
71-10-69	A3097-3	N/C	Apr 01/01
71-10-71	A3201-1, -2	N/C	Mar 01/01
71-10-72	A3295-3,-4	N/C	Oct 20/05
71-10-73	A3702-1	A	Nov 3/10
71-10-75	A3534-4	-	July 25/11
71-10-76	A3661-6,-7	A	Oct 4/13
71-10-77	A3559-1,-2	-	Aug 23/11
71-10-78	A3593-7	A	Nov 13/12
71-10-79	A3661-65	-	Nov 17/14
71-10-80	A3749-1	-	Sep 27/17
71-11-06	A2995-1	A	May 31/04
71-11-07	A2997-2	A	Apr 01/98
71-13-02	A1153-1B, -4A	C	Jul 01/00
71-13-03	A2273-2	N/C	May 01/00
71-13-12	A361-5/-9	D	Jan 20/10
71-13-14	A3068-1, -7 & A3068-3, -9	B	Jan 01/98
71-13-17	A3445-1, -10	M	Jul 31/09
71-13-34	A2273-3, -4	C	Sep 17/04
71-13-35	A3293-8	-	Nov 11/11
71-13-43	A3293-901	A	Nov 1/10
71-31-25	A2984-1	N/C	Nov 01/84
71-31-26	A2979-1, -3	K	12/13/17
78-26-42	A3701-2	N/C	May 15/09
78-31-01	A2865-7, -8	N/C	Apr 01/83
78-31-02	A2758-9	A	May 14/86
78-31-03	A2972-1, -2, -11, -21	C	Aug 12/02
78-31-04	A2973-1	A	Mar 01/02
78-31-05	A3081-1	N/C	May 01/87
78-31-06	A3080-2	N/C	May 01/87
78-31-07	A3335-13, -120	E	Feb 19/02
78-31-08	A3518-1	-	Nov 18/11
78-31-09	A3519-1	-	Nov 18/11
78-31-13	A3770-1	-	Sep 27/17
71-10-74	A3517-1	-	Nov 18/11
78-32-50	A3080-4	C	Jan 19/10
78-32-51	A3081-2	B	May 31/04
78-35-13	A3497-2	N/C	Sep 01/97
95-33-14	A3322-2	B	Dec 07/95



## Service Bulletins

<u>SERVICE BULLETIN</u>	<u>REVISION</u>	<u>DATE</u>	<u>CMM AFFECTED</u>
SB-A2711-78-1	N/C	12/01/87	71-10-35
SB-A2711-78-2	N/C	09/01/93	71-10-33, 71-10-35
SB-A2764-71-1	1	11/01/89	71-10-36
SB-A2866-71-1	N/C	05/01/91	71-10-18
SB-A2898-71-1	N/C	10/01/90	71-10-43
SB-A2956-78-1	N/C	11/01/87	71-10-39
SB-A2972-78-1	N/C	07/24/86	78-31-03
SB-A2972-78-2	N/C	02/06/89	78-31-03
SB-A2972-78-3	N/C	04/01/94	78-31-03
SB-A2973-78-1	N/C	03/01/02	78-31-04
SB-A3068-71-1	B	07/01/91	P/N – A3068-1
SB-A3068-71-2	N/C	10/01/91	P/N – A3068-1, -3
SB-A3068-71-3	N/C	3/15/97	71-13-14
SB-A3312-71-1	N/C	05/24/93	P/N – A3312-1
SB-A3312-71-2	N/C	10/17/95	P/N – A3312-2
SB-A361-71-1	N/C	10/01/91	71-10-47
SB-A361-71-2	1	11/15/06	71-13-12
SB-A6201-71-1	1	11/01/89	71-10-40
SB-A6201-71-2	N/C	10/01/93	71-10-40
SB-SS112-52-1	2	1/30/08	52-20-1
SB-A3482-71-1	N/C	6/15/09	71-10-58E